FIG. 1






FIG. 2








FIG. 4A

SCREEN FOR SELECTING PRINTING METHOD

- 1. OUTPUT TO ONE PRINTER
- 2. EQUALLY DIVIDED OFFIT

  WITH THE SAME SPECIFICATION, PRINTS ARE EQUALLY
  DIVIDED AND OUTPUT FROM MULTIPLE MACHINES
- 3. BROADCAST OUTPUT

WITH THE SAME SPECIFICATION, SPECIFIED NUMBER OF PRINTS ARE OUTPUT FROM EACH OF MULTIPLE MACHINES

4. INDIVIDUALLY SPECIFY

PRINTS ARE INDIVIDUALLY SET FOR EACH OF MULTIPLE MACHINES AND OUTPUT

5. BEST FIT

PRINTS ARE OUTPUT BY ONE OPTIMUM MACHINE SELECTED AMONG MULTIPLE MACHINES

FIG. 4B

DISPLAYED LIST OF SELECTABLE PRINTERS




FIG. 4C

SETTING SCREEN FOR EACH SELECTED PRINTER AT THE TIME OF OUTPUT




FIG. 5




FIG. 6




FIG. 7

